

## Plug-in Signal Conditioners K-UNIT


### VAR TRANSDUCER

#### Functions & Features

- Providing a DC output signal in proportion to AC reactive power
- DC output containing little ripple is ideal for computer input
- "Time division multiplication" method accepts distorted waveforms
- Isolation up to 2000 V AC
- High-density mounting

#### Typical Applications

- Centralized monitoring and control of power management system in a manufacturing facility or building



## MODEL: KERP-1[1][2][3]-[4][5]

### ORDERING INFORMATION

- Code number: KERP-1[1][2][3]-[4][5]  
Specify a code from below for each of [1] through [5].  
(e.g. KERP-11PA-C/Q)
- Calibration range (e.g. lag 1000 - 0 - lead 1000 var)
- VT ratio, CT ratio (e.g. VT 3300 / 110 V, CT 250 / 5 A)
- Special output range (For codes Z & 0)  
• Specify the specification for option code /Q  
(e.g. /C01/S01)

### CONFIGURATION

1: 3-phase / 3-wire

### [1] INPUT (unbalanced load)

(Voltage must be balanced.)

- 1: 110 V / 5 A AC
- 2: 110 V / 1 A AC
- 3: 220 V / 1 A AC
- 4: 220 V / 5 A AC

### [2] OUTPUT SIGNAL POLARITY

P: Negative in lag, positive in lead

M: Negative in lead, positive in lag

### [3] OUTPUT

Current

- A: 4 - 20 mA DC (Load resistance 600 Ω max.)
  - B: 2 - 10 mA DC (Load resistance 1200 Ω max.)
  - C: 1 - 5 mA DC (Load resistance 2400 Ω max.)
  - D: 0 - 20 mA DC (Load resistance 600 Ω max.)
  - E: 0 - 16 mA DC (Load resistance 750 Ω max.)
  - F: 0 - 10 mA DC (Load resistance 1200 Ω max.)
  - G: 0 - 1 mA DC (Load resistance 12 kΩ max.)
  - GW:** -1 - +1 mA DC (Load resistance 10 kΩ max.)
  - Z:** Specify current (See OUTPUT SPECIFICATIONS)
- Voltage
- 1: 0 - 10 mV DC (Load resistance 10 kΩ min.)
  - 2: 0 - 100 mV DC (Load resistance 100 kΩ min.)
  - 3: 0 - 1 V DC (Load resistance 1000 Ω min.)
  - 4: 0 - 10 V DC (Load resistance 10 kΩ min.)
  - 5: 0 - 5 V DC (Load resistance 5000 Ω min.)
  - 6: 1 - 5 V DC (Load resistance 5000 Ω min.)
  - 1W: -10 - +10 mV DC (Load resistance 10 kΩ min.)
  - 2W: -100 - +100 mV DC (Load resistance 100 kΩ min.)
  - 3W: -1 - +1 V DC (Load resistance 1000 Ω min.)
  - 4W: -10 - +10 V DC (Load resistance 10 kΩ min.)
  - 5W: -5 - +5 V DC (Load resistance 5000 Ω min.)
  - 0: Specify voltage (See OUTPUT SPECIFICATIONS)

### [4] AUXILIARY POWER SUPPLY

AC Power

- B: 100 V AC
- C: 110 V AC
- D: 115 V AC
- F: 120 V AC
- G: 200 V AC
- H: 220 V AC
- J: 240 V AC
- DC Power
- R: 24 V DC
- V: 48 V DC
- P: 110 V DC

### [5] OPTIONS

blank: none

/Q: With options (specify the specification)

### SPECIFICATIONS OF OPTION: Q (multiple selections)

COATING (For the detail, refer to our web site.)

/C01: Silicone coating

/C02: Polyurethane coating

/C03: Rubber coating

TERMINAL SCREW MATERIAL

/S01: Stainless steel



**Minimum span:** 5 mV

**Offset:** Max. 1.5 times span



**Load resistance:** Output drive 1 mA max. at  $\geq 0.5$  V

## ■ OPERATION DIAGRAM (example)

- Negative in lag, positive in lead



- Negative in lead, positive in lag



## INPUT SPECIFICATIONS

**Frequency:** 50 or 60 Hz

### • Voltage Input

**Operational range:** 0 – 120 % of rating

**Overload capacity:** 150 % of rating for 10 sec., 120 % continuous

### • Current Input

**Operational range:** 0 – 120 % of rating

**Overload capacity:** 1000 % of rating for 3 sec., 200 % for 10 sec., 120% continuous

### ■ How To Determine Var Range

Calibration Range [var] = (Measuring Range)  $\div$  ((VT Ratio)  $\times$  (CT Ratio))

Check that the required calibration range is within the available range in the table.

[example]

3-phase / 3-wire, measuring range 75 kvar,

VT 220 / 110 V, CT 250 / 5 A

$$(75 \times 10^3 \text{ [var]}) \div ((220 \div 110) \times (250 \div 5)) = 750 \text{ [var]}$$

### ■ INPUT RANGE

#### • 3-phase / 3-wire

INPUT STD.RANGE	AVAILABLE RANGE	BURDEN (VA)	
		VOLT.	CURR.
110V/1A	200 var	100 – 240 var	0.2 /phase
110V/5A	1000 var	500 – 1200 var	0.5/ph
220V/1A	400 var	200 – 480 var	0.4 /phase
220V/5A	2000 var	1000 – 2400 var	0.5/ph

## INSTALLATION

**Auxiliary power supply**

• AC: Operational voltage range: rating -15/+10 %, 50/60 Hz, approx. 2 VA

• DC: Operational voltage range: rating  $\pm 10$  %, or 85 – 150 V for 110 V rating, ripple 10 %p-p max., approx. 2 W (18 mA at 110 V)

**Operating temperature:** -10 to +55°C (14 to 131°F)

**Operating humidity:** 30 to 85 %RH (non-condensing)

**Mounting:** Surface or DIN rail

**Weight:** 450 g (0.99 lb)

## PERFORMANCE in percentage of span

**Accuracy:**  $\pm 0.5$  % (at  $23^\circ\text{C} \pm 10^\circ\text{C}$  or  $73.4^\circ\text{F} \pm 18^\circ\text{F}$ , 45 – 65 Hz)

**Response time:**  $\leq 2$  sec. (0 – 100 %  $\pm 1$  %)

**Ripple:** 0.5 %p-p max.(The output ripple may increase when there is great difference between the frequencies of input signal and power supply)

**Line voltage effect:**  $\pm 0.1$  % over voltage range

**Insulation resistance:**  $\geq 100$  MΩ with 500 V DC

**Dielectric strength:** 2000 V AC @ 1 minute

(voltage input to current input to output to auxiliary power to ground)

**Impulse withstand voltage:** 1.2 / 50  $\mu\text{sec}$ .,  $\pm 5$  kV (input to output or ground)

## OUTPUT SPECIFICATIONS

■ DC Current: 0 – 20 mA DC and  $\pm 1$  mA

**Minimum span:** 1 mA


**Offset:** Max. 1.5 times span

**Load resistance:** Output drive 12 V max.

■ DC Voltage: -10 – +12 V DC

## CONNECTION DIAGRAM


### ■ 3-PHASE/3-WIRE



\*CT Protector (model: CTM) attached to these terminals.


\*\*The transducer can be powered from the input voltage when the voltage is sufficiently stable and meets within the range of auxiliary power supply of the unit specified in the data sheet/instruction manual.

## EXTERNAL DIMENSIONS unit: mm [inch]



• When mounting, no extra space is needed between units.

**TERMINAL ASSIGNMENTS unit: mm [inch]**



Specifications are subject to change without notice.